



Example of wrong ratchet location on front

Cable wraps incorrectly

To much angle on the cable

Holes placed to far from center

REASSEMBLY OF RATCHETS IS FOR EXP-UP ONLY REASSEMBLY OF RATCHETS MAY CAUSE IMPROPER TIGHTENING OF LINKS

IMPORTANT
Chainrider's power life will be seriously reduced by careless lubrication. Use a 70% diesel fuel and 30% motor oil mixture on the track and rollers. Failure to keep the chain links loose will free rollers and result in broken gear case, heavy structure, stop chain, the loading the assembly.

U.S. Patent No. 6,877,051
Copyright © 2003 Chainrider